

A PORTION OF SEC. 10, T 21 N, R 5 E, W.M.



SCALE: 1" = 100'
 100 50 0 100 200
 CONTOUR INTERVAL = 2'

NO.	DESCRIPTION/DATE	BY
1	COUNTY COMMENTS 08/22/2018	ESM
2	COUNTY COMMENTS 11/15/2018	ESM
3	COUNTY COMMENTS 01/08/2019	ESM




ESM CONSULTING ENGINEERS LLC
 39400 8th Ave S, Suite 205
 Federal Way, WA 98003
 FEDERAL WAY (206) 508-6113
 EVERETT (425) 297-9900
 www.esmcivil.com
 Civil Engineering | Land Surveying | Project Management
 Public Works | Landscape Architecture


PACIFIC RACEWAYS
BUSINESS PARK
 EXISTING CONDITIONS
 KING COUNTY WASHINGTON

JOB NO.:	1263-002-016
DWG. NAME:	EX-01
DESIGNED BY:	TLS
DRAWN BY:	CJR
CHECKED BY:	
DATE:	01/08/2019
DATE OF PRINT:	

File: \\smb\eng\ESM\ESM\085\1263\002\016\plots\Eng_Clearing & Grading\EX-01.dwg
 Date: 1/8/2019 12:10 PM
 Plotted By: Scott Roberts



SECTION A-A
 SCALE: 1"=100' HORIZ.
 1"=10' VERT.



SECTION B-B
 SCALE: 1"=100' HORIZ.
 1"=10' VERT.

File: \\server\temp\ESM-085\1263\002\16\plans\Entry Clearing & Grading\GR-02.dwg
 Date: 7/27/2019 12:16 PM
 Plotted By: Carl Roberts

REVISIONS		
NO.	DESCRIPTION/DATE	BY
1	COUNTY COMMENTS 08/22/2018	ESM
2	COUNTY COMMENTS 11/15/2018	ESM
3	COUNTY COMMENTS 01/08/2019	ESM



ESM CONSULTING ENGINEERS LLC
 33400 8th Ave S, Suite 205
 Federal Way, WA 98003

www.esmcivil.com

Civil Engineering | Land Surveying | Project Management | Land Planning | Landscape Architecture


EVERETT | FEDERAL WAY | SEASIDE | EVERETT

(425) 838-6113
 (425) 377-9910


PACIFIC RACEWAYS
BUSINESS PARK
 CROSS SECTIONS

KING COUNTY WASHINGTON


JOB NO.:	1263-002-018
DWG. NAME:	GR-02
DESIGNED BY:	TLS
DRAWN BY:	CJR
CHECKED BY:	
DATE:	01/08/2019
DATE OF PRINT:	




RISER DETAIL




CROSS SECTION B-B




CROSS SECTION A-A




SEDIMENT POND
NOT TO SCALE



ORANGE PLASTIC FENCE DETAIL
NOT TO SCALE



ROCK-LINED CONSTRUCTION ENTRANCE DETAIL
NOT TO SCALE



TYPICAL FILTER FENCE DETAIL
NOT TO SCALE

1. ANY DAMAGE SHALL BE REPAIRED IMMEDIATELY.
2. IF CONCENTRATED FLOWS ARE EVIDENT UPHILL OF THE FENCE, THEY MUST BE INTERCEPTED AND CONVEYED TO A SEDIMENT TRAP OR POND.
3. IT IS IMPORTANT TO CHECK THE UPHILL SIDE OF THE FENCE FOR SIGNS OF THE FENCE CLOGGING AND ACTING AS A BARRIER TO FLOW AND THEN CAUSING CHANNELIZATION OF FLOWS PARALLEL TO THE FENCE. IF THIS OCCURS, REPLACE THE FENCE AND/OR REMOVE THE TRAPPED SEDIMENT.
4. SEDIMENT MUST BE REMOVED WHEN THE SEDIMENT IS 6" HIGH.
5. IF THE FILTER FABRIC HAS DETERIORATED DUE TO ULTRAVIOLET BREAKDOWN, IT SHALL BE REPLACED.

File: \\smc\env\ESM-0985\1263\002\016\pilot\pilot\pilot.dwg
 Date: 12/20/19 12:16 PM
 Project: 016 - 03.dwg
 Project: 016 - 03.dwg

REVISIONS		
NO.	DESCRIPTION/DATE	BY
1	COUNTY COMMENTS 08/22/2018	ESM
2	COUNTY COMMENTS 11/15/2018	ESM
3	COUNTY COMMENTS 01/08/2019	ESM

PREVOR L. STIFF
 REGISTERED PROFESSIONAL ENGINEER
 1/8/2019
 FEDERAL WAY (253) 838-6113
 EVERETT (425) 297-9920
ESM CONSULTING ENGINEERS LLC
 35400 8th Ave S, Suite 205
 Federal Way, WA 98003
 www.esmcivil.com
 Civil Engineering Public Works
 Land Surveying Project Management
 Land Planning Landscape Architecture

PACIFIC RACEWAYS
BUSINESS PARK
 T.E.S.C. & GRADING DETAILS
 KING COUNTY WASHINGTON
 JOB NO.: 1263-002-016
 DWG. NAME: GR-03
 DESIGNED BY: TLS
 DRAWN BY: CJR
 CHECKED BY:
 DATE: 01/08/2019
 DATE OF PRINT:
GR-03
 5 OF 5 SHEETS

