



Damaged Pipe Investigation





Discovery Park Environmental Learning Center February 16, 2017 6:30-8:30 p.m.










Meeting purpose Update you on the project Answer your questions Hear and learn from each other



Pa	ri	k	s



Overview

- Introductions

- Welcome WTD Director Mark Isaacson • Pipe Background Overview of King County's activities Current findings
- Upcoming work on W. Galer St.
- Questions




Ŗ	P	a	r	k	s



Opening Remarks

WTD Director Mark Isaacson



Pa	ri	k	s



Pipe Background

• Sends sewage and stormwater to Magnolia Wet Weather Facility

- Installed 2014-15
- Inspected and tested 2015
- Met EPA Consent Decree







Investigation starts September 2016 Tank did not fill during storm

- Inspections eliminate
 City sewers as source
- No indications of a problem from surface
- Pipe debris found in November

eliminate as source ns of a n surface ound in











Regular monitoring of surface conditions Alignment walks • Surveys Searched for other construction/surveys along pipe • Slope monitoring No signs of movement Rapid response initiated






Department of Natural Resources and Parks Wastewater Treatment Division

Safety and stability always the top priorities





W. Galer St. subsurface profile



Soil Types

Till and Till Like



Sand and Gravel

Clay and Silt



Wastewater Treatment Division

Thorndyke Ave. W

Silt and Fine Sand






Each gathers different information about soils along pipe No areas of soil loss near surface 2 locations of interest located deeper down

Geophysical Surveys – December 2016 Two types: microgravity & electrical resistivity













Drilling & grouting – December 2016

- 9 holes
- 6-inch diameter
- 135-145 feet deep
- At or near each pipe joint
- Casings inserted
- Grout inserted to replace lost soils
- Regular monitoring
- No sign of movement









ar	Pa	ırk	s



Subsurface Profile: Cross-section at Thorndyke


Till and Till Like

Sand and Gravel

Clay and Silt

Silt and Fine Sand

00	200	00
----	-----	----








Pipe Cleanout – January 2017

- California-based pipe cleanout specialty company hired
- Water rose on upstream (western) side of pipe during clean out
- Prevented camera inspection
- Pipe remains blocked











- - February March 2017
 - Meet with community Feb. 16
 - Start street work Feb. 21
 - Resume drilling near Thorndyke/W. Galer intersection
 - Insert grout in areas of soil loss o Traffic impacts o Vibration monitoring
 - Finish subsurface investigation
 - Tomography: sonar "pings" between boring holes

Upcoming work on W. Galer St.









- March June 2017 Finish drilling/grouting plan Complete tomography Evaluate repair options
- Internal repair
- Repair from surface
- Replacement
- Update community
- Initiate repair project











Your turn







Pa	ri	k	s



Staying informed








O www.kingcounty.gov/depts/dnrp/wtd/capital-projects/active/south-magnolia-cso-storage.aspx Oracle | PeopleSoft E 😰 Fleet 📴 KC - Ballard Siphon R 🗋 Safety/Training 🛂 King County, Washing 🚯 Community Services 🚯 WTD Emergency Resp 🗅 Forms and Training 🛅 Safety 🚯 Environmental and Co 🗭 GovDeliver King County Natural Resources and Parks Home Natural Resources and Parks Wastewater Treatment Capital projects Current projects Wastewater Treatment South Magnolia CSO control - storage Capital projects Magnolia Wet Weather Storage Facility at Smith Current projects Cove Denny Way Regulator Station upgrade **Project update** Eastgate Interceptor rehabilitation (lining) - Phase 3 Damaged Pipe Investigation Update meeting Eastside Interceptor lining Discovery Park Environmental Learning Center Fremont Siphon replacement 3801 Discovery Park Blvd, Seattle 6:30 - 8:30 p.m. Georgetown Wet Weather February 16, 2017 Treatment Station Last fall, King County began investigating a break in a pipe that carries Kent-Auburn conveyance system wastewater and stormwater to the County's Magnolia Wet Weather Storage improvements Facility near Smith Cove. Lake Hills and NW Lake At this meeting you can meet the project team, ask them questions, and hear

> FOR MORE INFORMATION Call: Doug Marsano at 206-423-0480 Email: doug.marsano@kingcounty.gov Search: "Magnolia storage" at kingcounty.gov Follow: @ KingCountyWTD on Twitter


















Pa	ri	k	s



How gravity and resistivity change underground

Less Porous Less Water Higher Density

Higher Gravity Higher Resistivity





More Porous More Water Lower Density


Lower Gravity Lower Resistivity







Electrical Resistivity Measures earth's resistance to electrical current flow Identifies voltage differences vertically and horizontally





Pa	ri	k	s